



# HAITI EARTHQUAKE

## ASCE/TCLEE RECONNAISSANCE PROJECT

**Presented by:**

**William Bruin, P.E**

**Principal Engineer**

**Halcrow Inc., Oakland**

**&**

**Alex Augustin**

**Assistant Civil Engineer**

**California State Lands Commission (MFD)**



# Haiti Earthquake Reconnaissance



- ◆ February 28 to March 6, 2010
- ◆ Two Groups: ASCE TCLEE and EERI
- ◆ 11 Lifeline Engineering Professionals
- ◆ Ports Team:
  - ◆ Stu Werner  
Seismic Systems
  - ◆ Nason McCullough  
CH2M-Hill
  - ◆ William Bruin  
Halcrow
  - ◆ Alex Augustin  
CSLC





# January 12, 2010 M7.0 Haiti Earthquake

- ◆ Previous Major Earthquakes:
  - ◆ June 3, 1770
  - ◆ 1860
- ◆ Date: January 12, 2010
- ◆ Earthquake Magnitude: 7.0
- ◆ Location: Port-au-Prince
- ◆ Hypocenter: ~ 6 miles
- ◆ Impacted Population: ~ 3,000,000
- ◆ Death Toll to Date: ~ 300,000
- ◆ Injured: ~ 300,000





# Port Sites Investigated





## Authorité Portuaire Nationale (APN)

- ◆ National Port Regulators
- ◆ Owns & Operates Port of Port-au-Prince
- ◆ In process of becoming Regulators only
- ◆ Port of Port-au-Prince
  - ◆ Largest and Busiest Container Port
    - ◆ 1,200 containers/day
    - ◆ 170,000 TEU/year
- ◆ Construction 1978-1980



# Authorité Portuaire Nationale (APN)

## a) Before Earthquake




# Authorité Portuaire Nationale (APN)

## b) After Earthquake


Note:

- B-2 denotes approximate borehole locations and borehole numbers from PPAP subsurface investigation by Rix, 2010





# Authorité Portuaire Nationale (APN)






# Authorit  Portuaire Nationale (APN)

## Condition Before Earthquake

- ◆ APN in process of Retrofitting both facilities
- ◆ Actual Condition Unknown (Assumed Poor)
- ◆ 18-in. Square Pre-stressed Concrete Piles
- ◆ Balanced Battered Pile Configuration
- ◆ Supported Gantry Container Crane, 2 mobile cranes
- ◆ **Configuration Similar to U.S**





# Authorité Portuaire Nationale (APN)

What Really Happened?



Very Large Lateral Spreading




Liquefaction & Translation of Wharf






# Authorité Portuaire Nationale (APN)

## North Wharf Warehouse Damage



a)



b)




c)




# Authorité Portuaire Nationale (APN)


## South Pier Condition

Before Earthquake





After Earthquake





a) Pile Damage Map



b) Map Legend



Red-Coded Pile



Yellow-Coded Pile

c) Examples of Red-Coded and Yellow-Coded Piles



# Authorité Portuaire Nationale (APN)

## North Wharf Conclusion

- ◆ Severe Structural Condition prior to earthquake
- ◆ Was not designed for Inertial and kinematic loads




# MOT Sites Investigated





# MOT Observations – Settlement




30  
Drown  
with  
collapse

~12 in. of  
Differential  
Settlement @  
Foot of Pier





# MOT Observations - Piping



**Severely Corroded  
Line Breaks with  
~12 in. of Settlement**



# MOT Observations - Settlement








# MOT Observations – Lateral Spreading





# Tank Farm Observations



- ◆ Full, unanchored tank rocked, buckled



# Tank Farm Observations



Tank Shell Buckling



# Anchorage Observations

- ◆ 15,000 gal. Diesel Tank
  - ◆ Partially Anchored (4 of 8 installed)
  - ◆ Anchor Uplift
  - ◆ Anchor Pullout
- ◆ Some anchorage better than nothing



Photos Courtesy of Eduardo Fierro





## Haiti Lessons Learned

- ◆ Liquefaction & lateral spreading caused significant structural damage
  - ◆ Consider kinematic loads in design
- ◆ Structural condition impacts performance
- ◆ Wharf-to-shore transition critical - piping/utilities/access
- ◆ Anchored tanks/equipment performed well
- ◆ Maintained piping performed well
- ◆ Post-event response plans are critical