



View north of west and south garage facades, May 10, 2007, 022.jpg



View west of east and north garage facades, May 10, 2007, 028.jpg



View east of Garage #2, May 10, 2007, 037.jpg



View southwest of coop, May 10, 2007, 025.jpg



View southeast of Shed #1, May 10, 2007, 021.jpg



View northeast of Shed #2, May 10, 2007 029.jpg



View northeast of Shed 3, May 10, 2007, 030.jpg



View east of Shed #4 and raised flower bed, May 10, 2007, 031.jpg



View northeast of Shed #5, May 10, 2007, 033.jpg





View east of shed with vegetation and greenhouse in back, May 10, 2007, 041.jpg




View south of Shed #7, May 10, 2007, 026.jpg

\*Map Name:

\*Year:



Key to USGS 7.5' quads depicted



SCALE 1:24,000

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
**PRIMARY RECORD**

Primary # \_\_\_\_\_  
HRI # \_\_\_\_\_  
Trinomial \_\_\_\_\_  
NRHP Status Code \_\_\_\_\_

Other Listings \_\_\_\_\_  
Review Code \_\_\_\_\_ Reviewer \_\_\_\_\_ Date \_\_\_\_\_

Page 1 of 6

\*Resource Name or #: Site 31

**P1. Other Identifier:** S31

\* **P2. Location:**  Not for Publication  Unrestricted \*a. County: Yolo

\* b. USGS Quad:

c. Address: 38023 County Road 16A

d. UTM: Zone 11; 604129 mE/ 4288666 mN NAD27 Parcel 638

e. Other Locational Data:

APN: 027-109-01-1-Southeast corner of Road16A and Road 98.

\* **P3a. Description:**

This property consists of a single-family residence and three ancillary structures, a barn/garage and two sheds. In addition, a modern warehouse is on the parcel. The house is rectangular in mass with a cross-gable roof clad with composition shingles. Siding on the house is aluminum with simulated horizontal boards and there are louvers in the gable ends. The house is on a concrete slab foundation and there are exterior brick chimneys on the west central façade and the south end of the north façade. The east and west façades have brick wainscoting. Fenestration is symmetrical and consists of vertical aluminum siding modern windows. A bay window is present on the main (north) façade. There are several entries into the house, all accessed by a single concrete riser. The east central entry is protected by a gable portico. The house is surrounded by lawn and is separated from the remainder of the property by a brick wall and a wood fence on the east and a three-rail wood fence on the other three sides.

\* **P3b. Resource Attributes:** HP2. Single family home HP4. Ancillary buildings; HP33, Farm/Ranch

\* **P4. Resources Present:**  Building  Structure  Object  Site  District  Element of District  Other (Isolates, etc.)



\* **P5b. Description of Photo:**

View southwest of house, May 10, 2007; 058.jpg

\* **P6. Date Constructed/Age & Sources:**

Historic  Prehistoric  Both  
ca. 1900, remolded 1930s, 1990s

\* **P7. Owner and Address:**

Leonard, Richard E. and Laura E.,  
38023 Creek 16A; Woodland, CA  
95695

\* **P8. Recorded by:**

Mary L. Maniery, PAR Environmental  
Services, Inc., PO Box 160756,  
Sacramento, CA 95816

\* **P9. Date Recorded:** 6/21/2007

\* **P10. Survey Type:**

Intensive survey of PG&E pipeline  
corridor

\* **P11. Citation:** Wohlgemuth et al. 2007. Cultural Resources Survey for PG&E Line 407 Project, Placer, Sacramento, Sutter, and Yolo Counties, California.

\* **Attachments:**  None  Location Map  Sketch Map  Continuation Sheet  Building, Structure, and Object Record  
 Archaeological Record  District Record  Linear Feature Record  Milling Station Record  Rock Art Record  
 Artifact Record  Photograph Record  Other:

DPR523A (1/95)

\*Required Information

# BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 6

\*NRHP Status Code:

\*Resource Name or #: Site 31

**B1. Historic Name:** N/A

**B2. Common Name:** N/A

**B3. Original Use:** Farmstead

**B4. Present Use:** Farmstead

\* **B5. Architectural Style:** n/a

\* **B6. Construction History:**

According to Carol Gorman, her father and mother purchased this property in the 1930s. At that time the house was used as a bunkhouse and it was depicted on a 1905 map. Her parents completely remodeled and enlarged the structure through the years, resulting in the appearance today. Alterations include aluminum slider windows and sliding glass doors, creation of a bay

\* **B7. Moved?**  No  Yes  Unknown

**Date:**

**Original Location:**

\* **B8. Related Features:**

agricultural fields

**B9a. Architect:** Unknown

**B9b. Builder:** Unknown

\* **B10. Significance: Theme:** Agriculture/Farm Architecture

**Area:** Yolo County

**Period of Significance:** N/A

**Property Type:** N/A

**Applicable Criteria:** N/A

Development of this portion of Yolo County began in the 1850s with scattered farmsteads associated with wheat and grain farming. Over time these large-scale farms were divided and sold, or expanded and shared among family members, resulting in construction of additional residences. In 1879 this property was owned the heirs of Jas. A. Hutton. James Hutton established a ranch by 1892 and the town of Cacheville (now Yolo) grew up around his ranch site (Les 1986). This parcel was part of Hutton's holdings. It was subdivided into smaller parcels by 1926 was owned by Emmanuel Heuberald at that time. This property was built in the 1920s likely by Heuberald and was bought and enlarged in the 1930s by the Gorman family.

While the property is associated with local farming, key elements, such as the house, have been heavily modified and no longer resemble the 1920s farmstead design. The original appearance of the house in particular has been altered by additions, window replacement, and exterior fabric modifications and does not retain original integrity. As a result of the loss on integrity, this property no longer retains adequate integrity to qualify for inclusion in the National Register of Historic Places or the California Register of Historic Resources under any criteria.

**B11. Additional Resource Attributes:** None

\* **B12. References:**

DePue & Co.  
1879 Illustrated History of Yolo County California. DePue & Co, San Francisco. On file, California History Room, California State Library, Sacramento, CA.


**B13. Remarks:**

none

\* **B14. Evaluator:** Mary L. Maniery

\* **Date of Evaluation:** 6/21/2007

(This space reserved for official comments.)



\*Recorded By: Mary L. Maniery

\*Date: 6/21/2007  Continuation  Update

P3. Description Cont.

A modern, metal-clad storehouse is located east of the house. The other three ancillary buildings east of the house are sheds and a garage, all more than 50 years of age.

Shed #1 is at the far eastern end of the property, just north of the garage. This shed is a wood-frame structure clad with galvanized corrugated metal sheets. The shed roof is also metal clad with exposed rafter tails on the west sides. The shed is accessed by a double door with a central latch.

The garage appears to have originally served as a barn. It has a gable-with-shed-roof clad with galvanized corrugated metal sheets. The facades are clad with vertical board siding. A top sliding wood double bay door is on the west side and a pedestrian door is on the north.

The second shed is west of shed #1 near the road. It is a rectangular, gable-roofed structure clad with the sheets of galvanized corrugated metal. Original windows (one on each side) have been replaced with vertical sliding aluminum windows. A door, protected by a portico, is present on the south side. The shed is on a concrete slab foundation.

B6. Construction History:

creation of a bay window, exterior chimney, brick skirt and replacement of exterior fabric. The barn and sheds are contemporary with the original house (circa 1910s) but are now clad with metal. The warehouse is less than 20 years old.

B12. References:

Gorman, Carol  
2007 Personal communication with Mary Maniery, PAR Environmental Services, Inc., Sacramento.

Les, Kathleen  
1986 Yolo County Historic Resources Survey. Les-Thomas Associates and Yolo County Community Development Agency.

Lewis Publication Company  
1891 Yolo County History: A Memorial and Biographical History of Northern California. Chicago.

Proctor  
1926 Official Map of Yolo County, California. On file, California History room, California State Library, Sacramento, CA.



View east of shed #1, May 10, 2007, 061.jpg





View southeast of garage, May 10, 2007, 060.jpg




View west of shed #2, May 10, 2007, 063.jpg

\*Map Name:

\*Year:



Key to USGS 7.5' quads depicted



SCALE 1:24,000

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
**PRIMARY RECORD**

Primary # P-57-000407

HRI # \_\_\_\_\_

Trinomial \_\_\_\_\_

NRHP Status Code 7

Other Listings \_\_\_\_\_

Review Code \_\_\_\_\_

Reviewer \_\_\_\_\_

Date \_\_\_\_\_

Page 1 of 3

\*Resource Name or # (Assigned by recorder) REF 5-H

**P1. Other Identifier:** 38871 County Road 16A

\*P2. Location:  Not for Publication  Unrestricted

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

\*a. County Yolo

\*b. USGS 7.5' Quad Woodland Date 1952 photorevised 1968 T \_\_\_\_\_; R \_\_\_\_\_; \_\_\_\_\_ 1/4 of Sec \_\_\_\_\_; \_\_\_\_\_ B.M. (Map#5141)

c. Address 38871 County Road 16A City Woodland Zip 95695

d. UTM: (give more than one for large and/or linear resources) Zone (10); (605460mE)<sub>mE</sub>/ (4288640mN)<sub>mN</sub>

e. Other Locational Data: (e.g., parcel #, directions to resource, elevation, etc., as appropriate)

APN: 27-240-02-1

\*P3a. Description: (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

Located on a 20 acre parcel, the house at 38871 County Road 16A is a one-story cottage with a modern detached garage and barn to the south. The house sits close to the road and a gravel driveway running south provides access to the garage. Sitting on a brick foundation with an irregular shaped plan, it is covered with a gable on hip roof as shown in Photograph 1. There are two small attached front gables over the covered entry. The covered entry is supported by paired tapered columns and a wooden balustrade with attached benches. Fenestration consists of one-over-one double hung wood sash arranged in pairs and singles. The fenestration is surrounded by wide wood trim with a slip sill. On the east side there is a bay window with a pent roof. Also on the east side is an exterior end brick chimney with a stepped shoulder and a porch on the southeast corner.

\*P3b. Resource Attributes: (List attributes and codes) HP33 Farm/ranch

\*P4. Resources Present:  Building  Structure  Object  Site  District  Element of District  Other (Isolates, etc.)

P5a. Photo of Drawing (Photo required for buildings, structures, and objects.)



P5b. Description of Photo: (View, date, accession #) Photograph # 1, camera facing southwest, April 5, 2002

\*P6. Date Constructed/Age and Sources:  
 Historic  Prehistoric  Both  
circa 1910s

\*P7. Owner and Address:  
Michael and Treva Valentine  
38871 County Road 16A  
Woodland, CA 95695-9126 R003

\*P8. Recorded by: (Name, affiliation, address)  
Amanda Blosser and Andy Walters  
JRP Historical Consulting Services,  
1490 Drew Ave, Suite 110, Davis,  
CA 95616

\*P9. Date Recorded: April 5, 2002

\*P10. Survey Type: (Describe) Intensive

\*P11. Report Citation: (Cite survey report and other sources, or enter "none.") JRP Historical Consulting Services, AFC Enron Roseville Energy Facility, Yolo, Sacramento, Placer and Sutter Counties, June 2002

\*Attachments: NONE  Location Map  Sketch Map  Continuation Sheet  Building, Structure, and Object Record  Archaeological Record  District Record  Linear Feature Record  Milling Station Record  Rock Art Record  Artifact Record  Photograph Record  Other (list) \_\_\_\_\_

DPR 523A (1/95)

\*Required Information


CEC 5-2000

**P3a. Description (continued):**

This porch has an engaged roof and is supported by tapered wood columns.

Located on the south side of the house is a one story detached garage. Built of modern materials, it covered with a hip roof sheathed in composition shingles. There are two garage doors on the east side. The wood plank barn sits south of the garage and is covered with a front gable roof. The roof is sheathed with corrugated metal. A door is located on the east side of the barn. Trees and bushes run along the driveway on the east side and obscure view of the barn and garage from the road.

**Location Map**



\*Recorded By: Mary L. Maniery

\*Date: 6/10/2007  Continuation  Update

This property was recorded in 2002 by JRP Historical Consulting Services. It was revisited on May 7, 2007 by Mary L. Maniery, PAR Environmental Services, Inc.

The chimney described by JRP on the east side of the house is flanked by decorative window sets, each with two windows and each window with nine panes. A recessed entry is centered on the east façade. A decorative wrought iron fence extends out (east) from the chimney.

Since 2002 the garage has been expanded north towards the house with a hip-on-gable-roof addition. This addition has shiplap siding, symmetrical double hung windows and an entry on the north façade. An elevated wood deck connects the house and the garage/addition. It has an open wood beam cover supported by columns.

A barn is south of the garage. It is a wood-frame structure covered with corrugated metal sheets. The gable roof is also covered with metal. The roof peak extends out on the south side to accommodate a hay hook. The south side has two metal-covered sliding wooden doors.

A garden is on the west side of the property.

B12. References:

DePue and Co.  
1879 Illustrated History of Yolo County. DePue & Co., San Francisco. On file, California History Room, California State Library, Sacramento.

Page 2 of 6

\*Resource Name or #: (UPDATE)

\*Recorded By: Mary L. Maniery

\*Date: 6/8/2007

Continuation

Update

B12. References:

Proctor

1915 Official Map of Yolo County. On file, California History Room, California State Library, Sacramento.

1926 Official Map of Yolo County. On file, California History Room, California State Library, Sacramento

# BUILDING, STRUCTURE, AND OBJECT RECORD

Page 3 of 6

\*NRHP Status Code:  
\*Resource Name or #: (UPDATE)

**B1. Historic Name:** n/A

**B2. Common Name:** n/A

**B3. Original Use:** farmstead

**B4. Present Use:** farmstead

\* **B5. Architectural Style:**

\* **B6. Construction History:**

JRP notes that this house was built in the 1910s. It retains little appearance of this early construction date. A massive addition, connecting deck and some replacement windows, all added since 2002, have overwhelmed the original structure. The barn, however, does reflect an early 1910s construction date, although it has been covered with metal sheeting.

\* **B7. Moved?**  No  Yes  Unknown

**Date:**

**Original Location:**

\* **B8. Related Features:**

Agricultural fields

**B9a. Architect:** Unknown

**B9b. Builder:** Unknown

\* **B10. Significance: Theme:** Agriculture

**Area:**

**Period of Significance:** n/A

**Property Type:** n/A

**Applicable Criteria:** n/A

Settlement and farming in this area of Yolo County began by 1850s, focusing on animal husbandry and grain production. Following a major flood in 1878 many farmers left the region. This property, part of a 413-acre parcel, was acquired by George B. Eustis and William V. Jubb soon after the flood, likely on speculation. Eustis was the sole owner by 1915. He subdivided the large parcel into 8 lots by 1926 and two of those were then subdivided into 8 additional lots (DePue 1879; Proctor 1915, 1926). After the parcel was subdivided this lot was owned by Thornton M. Craig, a local merchant. It is probable that the house was built for Craig between 1915 and 1925.

While the property is associated with local farming, key elements, such as the house, have been heavily modified and no longer resemble the 1910s-1920s farmstead design. The original appearance of the house in particular has been altered by additions and window replacements and does not retain original integrity. As a result of the loss on integrity, this property no longer retains adequate integrity to qualify for inclusion in the National Register of Historic Places or the California Register of Historic Resources under any criteria.

**B11. Additional Resource Attributes:** none

\* **B12. References:**

Ashley, W.  
1900 Official Map of Yolo County. On file, California History Room,  
California State Library, Sacramento


**B13. Remarks:**

None

\* **B14. Evaluator:** Mary L. Maniery

\* **Date of Evaluation:** 6/8/2007

(This space reserved for official comments.)



\*Recorded By: Mary L. Maniery

\*Date: 6/10/2007  Continuation  Update

This property was recorded in 2002 by JRP Historical Consulting Services. It was revisited on May 7, 2007 by Mary L. Maniery, PAR Environmental Services, Inc.

The chimney described by JRP on the east side of the house is flanked by decorative window sets, each with two windows and each window with nine panes. A recessed entry is centered on the east façade. A decorative wrought iron fence extends out (east) from the chimney.

Since 2002 the garage has been expanded north towards the house with a hip-on-gable-roof addition. This addition has shiplap siding, symmetrical double hung windows and an entry on the north façade. An elevated wood deck connects the house and the garage/addition. It has an open wood beam cover supported by columns.

A barn is south of the garage. It is a wood-frame structure covered with corrugated metal sheets. The gable roof is also covered with metal. The roof peak extends out on the south side to accommodate a hay hook. The south side has two metal-covered sliding wooden doors.

A garden is on the west side of the property.

B12. References:

DePue and Co.  
1879 Illustrated History of Yolo County. DePue & Co., San Francisco. On file, California History Room, California State Library, Sacramento.

Page 5 of 6

\*Resource Name or #: (UPDATE)

\*Recorded By: Mary L. Maniery

\*Date: 6/7/2007

Continuation

Update





View west of barn, May 7, 2007, 046.jpg

Page 6 of 6


\*Resource Name or #: (UPDATE)

\*Map Name:

\*Year:



Key to USGS 7.5' quads depicted



SCALE 1:24,000

State of California - The Resources Agency  
DEPARTMENT OF PARKS AND RECREATION  
**PRIMARY RECORD**

Primary # \_\_\_\_\_  
HRI # \_\_\_\_\_  
Trinomial \_\_\_\_\_  
NRHP Status Code \_\_\_\_\_

Other Listings \_\_\_\_\_  
Review Code \_\_\_\_\_ Reviewer \_\_\_\_\_ Date \_\_\_\_\_

Page 1 of 6

\*Resource Name or #: Site 26

P1. Other Identifier: S26

\* P2. Location:  Not for Publication  Unrestricted \*a. County: Yolo

\* b. USGS Quad: Woodland (1952; photorevised 1980); T10N R2E, ; MDBM

c. Address: 14020 Country Road 99A, Parcel 457

d. UTM: See Continuation Sheet

e. Other Locational Data:

APN 027-160-08-1-Southwest corner of Road 17 and Rad 99A.

\* P3a. Description:

This property consists of a house and, barns surrounded by mature trees and shrubs. The property is on the east side of agricultural fields and serves as a ranch/farmstead.

House: The house (#1) has a two-story, gable-roofed rectangular center with a one-story, cross-gable addition and a on the north side and a one-story wrap-around shed-roof addition on the north and west sides.

The roofs are covered with composition shingles. The two-story section has a wood louver in one gable end and a window in the other. The window appears to be an addition. Siding throughout the structure is channeled horizontal boards.

\* P3b. Resource Attributes:

\* P4. Resources Present:  Building  Structure  Object  Site  District  Element of District  Other (Isolates, etc.)



\*P5b. Description of Photo:

View of house, northwest, May 7, 2007, 01915.jpg

\*P6. Date Constructed/Age & Sources:

Historic  Prehistoric  Both  
ca. 1880s

\*P7. Owner and Address:

Douglas W. and Diane P. Beard,  
14080 Creek 99A; Woodland, CA  
95695

\*P8. Recorded by:

Mary L. Maniery, PAR Environmental  
Services, Inc., PO Box 160756,  
Sacramento, CA 95816

\*P9. Date Recorded: 6/7/2007

\*P10. Survey Type:

Intensive survey of PG&E pipeline  
corridor

\* P11. Citation: Wohlgemuth et al. 2007. Cultural Resources Survey for PG&E Line 407 Project, Placer, Sacramento, Sutter, and Yolo Counties, California.

\* Attachments:  None  Location Map  Sketch Map  Continuation Sheet  Building, Structure, and Object Record  
 Archaeological Record  District Record  Linear Feature Record  Milling Station Record  Rock Art Record  
 Artifact Record  Photograph Record  Other:

# BUILDING, STRUCTURE, AND OBJECT RECORD

Page 2 of 6

\*NRHP Status Code:

\*Resource Name or #: Site 26

B1. Historic Name: n/A

B2. Common Name: n/A

B3. Original Use: farmstead

B4. Present Use: farmstead

\* B5. Architectural Style: Folk Victorian with modifications

\* B6. Construction History:

The house is depicted on a 1905 map and was likely built by the late 1880s. Since then it has had two single story additions and some original window openings have been boarded over. New aluminum sliders are present as well. These alterations have changed the overall appearance and integrity of the house. The outbuildings, while contemporary with the house, have

\* B7. Moved?  No  Yes  Unknown

Date:

Original Location:

\* B8. Related Features:

Agricultural fields

B9a. Architect: Unknown

B9b. Builder: Unknown

\* B10. Significance: Theme: Agriculture

Area: Yolo County

Period of Significance: n/A

Property Type: n/A

Applicable Criteria: n/A

Settlement and farming in this area of Yolo County began by 1850s, focusing on animal husbandry and grain production.

Following a major flood in 1878 many farmers left the region. This property, part of a 413-acre parcel, was acquired by George B. Eustis and William V. Jubb soon after the flood, likely on speculation. Eustis was the sole owner by 1915. He subdivided the large parcel into 8 lots by 1926 and two of those were then subdivided into 8 additional lots (DePue 1879; Proctor 1915, 1926). This property was in place by 1905 and as part of the larger parcel; however, the original owner is unknown. After subdivision it remained on a 20-acre parcel.

While the core of the house is visible, two additions and window replacements have altered the appearance of a Folk Victorian and compromised the overall integrity. As a result of the loss on integrity, this property no longer retains adequate integrity to qualify for inclusion in the National Register of Historic Places or the California Register of Historic Resources under any criteria.

B11. Additional Resource Attributes: none

\* B12. References:

Ashley, W.

1900 Official Map of Yolo County. On file, California History Room, California State Library, Sacramento.


B13. Remarks:

None

\* B14. Evaluator: Mary L., Maniery

\* Date of Evaluation: 6/21/2007

(This space reserved for official comments.)



\*Recorded By: Mary L. Maniery

\*Date: 6/21/2007

Continuation  Update

P3. Description:

Fenestration is symmetrical on the main structure. The front entry is on the south façade and is centrally located, accessed by two concrete risers, and flanked by large aluminum slider windows with wood shutters. The entry is protected by a gable-roofed portico supported on 2" x 4" posts. The upper story has two aluminum sliding windows on the south façade and three original double hung wood frame windows over two aluminum slider replacements are on the east side. A boarded-over window opening is visible on the upper story of the north façade but the addition resulted in the replacement of the other original windows on this and the west façade.

The two additions to the house each accommodate an extra room. The gable roof addition has one aluminum slider with shutters on the east side and exposed rafter tails. The wrap-around addition has a small double-hung window on the east side an entry on the north. It also has exposed rafter tails.

The house is surrounded by palms, oak, conifer, and other trees, hedges and lawn. A white picket fence separates the property from the road and fields on the north and east. A barn (structure 2) is located west of the house. It is a one-story wood-frame rectangular structure with a gable roof. A shed-roof addition extends off the south façade and open-sided covered work areas/car ports are on the north and west sides. A small (8-10 foot square) gable roof addition with a pedestrian door is on the east side. The roof and some façades are covered with corrugated metal sheets. The west façade and the gable ends have vertical board or plywood siding. Two windows are on the south façade and three pedestrian doors are on the east.

A second barn (#3) is west of Structure #2. It is a wood-frame, gable-roof structure covered with vertical board siding. In several places corrugated metal sheets cover the wood siding. The roof is covered with the metal sheets. A small one-story shed-roof

P3. Description:

room extends off the east façade. All doors and windows are missing although barn doors appear to have been present on the south façade. A circular water tank (#4) is located northwest of Barn #3. It is galvanized metal and is covered with a flat metal sheet.

B6. Construction History:

also had alterations, changes in exterior fabric, removal of windows and other modifications.

B12. References:

DePue and Co.  
1879 Illustrated History of Yolo County. DePue & Co., San Francisco. On file, California History Room, California State Library, Sacramento.

Proctor  
1915 Official Map of Yolo County. On file, California History Room, California State Library, Sacramento.

1926 Official Map of Yolo County. On file, California History Room, California State Library, Sacramento



House and addition, view southwest of main house and addition, May 7, 2007, 914.jpg





Barn #2, view northeast, May 7, 2007, 922.jpg




Barn #3 and water tank (#4), view northeast, May 7, 2007

\*Map Name:

\*Year:



Key to USGS 7.5' quads depicted



SCALE 1:24,000