

Appendix A
Photographs - Remnants of Port Costa Wharf

Photographs of Remaining Port Costa Wharf

Photo #: Appendix A-01

Description: Timber deck platform access, south side, camera facing northeast.



Photo #: Appendix A-02

Description: South side access walk, camera facing northeast.



Photographs of Remaining Port Costa Wharf

Photo #: Appendix A-03

Description: North side access walk, camera facing west.



Photo #: Appendix A-04

Description: Remnants of the main wharf, camera facing northwest.



Photographs of Remaining Port Costa Wharf

Photo #: Appendix A-05

Description: Stand alone dolphin, south side, camera facing east.



Photo #: Appendix A-06

Description: View of the main wharf deck and southern dolphin, camera facing southwest.



Photographs of Remaining Port Costa Wharf

Photo #: Appendix A-07

Description: Timber pile dolphins north of the former wharf, camera facing southwest

